


PRICE LIST OF REPAIRS
—FOR—
HEEBNERS'
PENNSYLVANIA THRESHING MACHINE,
FOR ONE-HORSE POWER,
MANUFACTURED BY
HEEBNER & SONS,
LANSDALE, MONTGOMERY COUNTY, PA.
BRANCH HOUSE—PORTLAND, ME.

READ THIS.



In ordering repairs, be sure to give the name plainly, also the number, just as they are given in this price list, and also give the name of the machine and the year in which it was made.

SPECIAL NOTICE.

We have often been imposed upon by parties from a distance, who have ordered repairs to be sent to them by express C. O. D., and would not receive them, consequently the repairs would come back to us with two express charges to pay; and others would order on credit and then forget to pay us. In consideration of the above facts, we have decided not to send away any repairs until we have first received pay for them. We shall adhere strictly to this rule in the future.

Money may be sent to us by P. O. Order, Draft, Postal Note, or in a Registered Letter. Address

HEEBNER & SONS,
LANSDALE, PA.

PRICE LIST OF REPAIRS FOR HEEBNERS' PENNSYLVANIA THRESHING MACHINE FOR ONE HORSE.

	NO.	PRICE.
Cylinder complete with steel teeth.....		\$23 00
Cylinder shaft, steel.....		2 00
Cylinder boxes, each.....	WI 1	25
Cylinder box set screw.....		05
Cylinder pulley, 6 inch diameter.....	1	50
Cylinder pulley pawl.....	3	25
Cylinder pulley pawl hub with screw.....		50
Cylinder teeth, steel, with nut.....		10
Cylinder teeth, steel, without nut.....		09
Concave with teeth complete.....	7	00
Concave without teeth and bolster.....	2	75
Concave bolster, wood.....		75
Concave lifter.....	IX	20

	NO.	PRICE.
Concave teeth, steel, with nut.....	\$	11
Concave teeth, steel, without nut.....		10
Concave adjusting screw.....		50
Concave adjusting screw nut.....	O	30
Iron thresher side.....	A	3 00
Iron thresher side.....	B	3 00
Shaker crank shaft.....		2 25
Shaker wheel, 22½ inch diameter.....		3 75
Shaker wheel set screws, each.....		15
Table-hook and eye-bolt, each.....		05
Table brace socket.....	U	10
Fan driving cone pulley, on crank shaft.....	14S	1 25
Tightner pulley for main belt	6G	1 15
Tightner pulley hanger.....	7G	1 00
Tightner pulley and hanger, complete.....		2 15
Shaker pitman, wood, with box.....		1 00
Upper shaker bottom, perforated galvanized iron.....		3 50
Lower shaker bottom, plain sheet iron.....		1 15
Shaker hanger.....	3S	35

	NO.	PRICE.
Shaker hanger.....	4S	\$ 40
Shaker hanger.....	5S	35
Shaker hanger with set screw.....	7SR	60
Shaker hanger.....	7SL	60
Shaker hanger.....	8S	35
Upper shaker hanger gudgeon.....	1S	10
Lower shaker hanger gudgeon.....	2S	25
Lower shaker hanger gudgeon.....	22S	25
Steel beater forks, shaft and tines.....		1 00
Beater fork shaft box.....		05
Balance grain stop (or apron), in shaker.....		1 00
Balance grain stop weight.....	14G	35
Sheet iron sieve.....		2 00
Wire sieves, each.....		1 00
Sieve holder, on shoe.....	97	10
Sieve holder, on shoe.....	98	10
Sieve irons, on sieve, each.....		05
Shoe hanger irons, each.....		40
Rock shaft, with wrist.....	21S	1 25

	NO.	PRICE.
Upper rock shaft box.....	16S	\$ 50
Lower rock shaft box.....	15S	35
Fan shaft.....		1 00
Fan arms, with set screw.....	12S	50
Fan shaft box and support, each.....	11S	50
Shoe pitman, wood.....		35
Shoe pitman gudgeon, under shoe.....		35
Rock shaft pitman.....		35
Grain spout.....		80