
Good Points on Plows

Price List

HAMBURG PLOW REPAIRS

to fit the Leading Lines



See Inside Cover for Complete Index

Sold by

R. Herschel Mfg. Company

Auburn, N. Y.

Foreword

Hamburg plow repairs have been on the market for nearly fifty years. They are made of *the best materials*, are *correctly chilled*, they *will fit*, and they *will wear*.

The great variety of parts which we can supply to fit the leading lines will enable you, when placing your orders with us, to save both shipping time and expense.

To The Trade

We have tried to make this list as simple as possible and by referring to index below we believe you will be able to readily find any item you need in plow parts.

Index

	Page
To fit Burch	12
To fit Cambridge	11-12
To fit Chicopee	16
To fit Deere	8-9
To fit East Aurora	15
To fit Eddy	16
To fit Ferguson	14
To fit Imperial	12-13-14
To fit International	14
To fit Janesville	15
To fit Leroy	11
To fit Moline	16
To fit Munnsville	15
To fit Oliver	3-4-5
To fit P. & O.	12
To fit Peerless	16
To fit Randolph	16
To fit Syracuse	5-6-7-8
To fit Wiard	9-10-11

Prices subject to change without notice.

Not responsible for errors.

In addition to parts listed by Hamburg, we carry the following in Auburn Stock:

Caledonia Plow Shares

		To Fit	List Ea.
26	Solid Shares R.H....	Cambridge	\$.85
27	Solid Shares R.H....	Cambridge	.90
10-29	Hillside Shares.....	Cambridge	1.05
10-29	Jointer Shares R.H..	Cambridge	.45
2	Solid Shares Plain R.H..	Dutton	.90
2	Jointer Shares R.H.....	Dutton	.25
2	Landsides R.H.....	Dutton	1.50
4S	Solid Shares.....	Eddy	.95
WP323	Solid Shares R.H.....	Moline	1.20
WP325	Solid Shares R.H.....	Moline	1.20
WP577 12"	Solid Shares R.H.....	Moline	1.20
WP577 14"	Solid Shares R.H.....	Moline	1.20
WP332	Landsides R.H.....	Moline	1.30
WP52	Jointer Shares.....	Moline	.25
WP56	Jointer Shares.....	Moline	.25
	Jointer Shares.....	Munnsville	.25
84DF	Landsides L.H.....	Oliver	1.45
A	Solid Shares R.H....	Robinson	.80
B.C.D.	Solid Shares R.H....	Robinson	1.00
B.C.	Cutter Shares R.H....	Robinson	1.05
B.C.D.	Landsides R.H.....	Robinson	1.60
Robinson	Jointer Shares R.H...	Robinson	.35
823	Hillside Shares.....	Syracuse	.80
CE7	Jointer Shares (Hillside)		
		Syracuse	.25
CC21	Shoes	Syracuse	.70

R. HERSCHEL MANUFACTURING CO.
AUBURN, N. Y.

GOOD REPAIRS MAKE A GOOD PLOW BETTER

To Fit OLIVER

Solid Shares, Right Hand

A	\$.25
AC, DS or X	.30
B	.30
BC, DS or X	.42
B5	.65
10 S, DS, or X	.45
13 S, DS, or X	.55
19 S, DS or X	.60
20 S, DS or X	.65
40 S, C, DS, DSS	.70
40 SNY	.70
40 XX	.85
E, S, C, DS, SNY	.70
OVG 15	.60
OVG 24	.75
9 Vin.	.90
50-16 in.	1.70
3 X	1.05
82 DS	.75
82 SNY	.75
83	.85
83 SNY	.85
83 DS 10 X	.85
83 DS 11 X	.85
84-12 in.	.85
84-13 in.	.95
84 and 88 SNY	.85
84 and 88 DS 12 X	.85
84 and 88 DDS 12 S.	.85
84 and 88 DDS 12	.85
84 and 88 DS 14	1.05
84 and 88 KDS 11 X cutter	.95

TO FIT OLIVER

(Solid Shares, Continued)

403	\$.90
404	1.00
405-12 in.	1.10
405-14 in.	1.20
101-8 in.	.85
101-10 in.	.90
101-10 in. Cutter	1.05
101-12 in.	1.00
102-7 in.	.85
221 X-12 in.	1.00
222 XX to fit No. 11 Sulky	1.55
141-12 in. (Bolt)	1.15
141-14 in. (Bolt)	1.35
141-12 in. Q. D.	1.40
141-14 in. Q. D.	1.60
141-12 in. SNY (Bolt)	1.15
141-14 in. SNY (Bolt)	1.35
141-12 in. SNY Q. D.	1.40
141-14 in. SNY Q. D.	1.60
NC 150-14 in. (Bolt)	1.70
NC 150-16 in. (Bolt)	1.80
NC 150-14 in. Q. D.	1.95
NC 150-16 in. Q. D.	2.05
98 Wings	.55
99 Wings	.55
99 X Slips	.25
NC 23-12 in. Q. D.	1.40
NC 23-14 in. Q. D.	1.60
NC 23-16 in. Q. D.	2.05
C 1 X 7	.65
NC 3-18 in. S.	2.00

Solid Shares, Left Hand

40 S, C, DS, DSLN, SLN, NYS	\$.70
40 XX	.85

THEY ARE WORTH THE PRICE

TO FIT OLIVER

(Solid Shares, Left Hand,
Continued)

E, S, C, DS, SLN,	
DSL N	\$.70
3 X	1.05
83	.85
84-12 in.	.85
84-13 in.	.95
84 and 91 DS 11 X	.85
84 and 91 DS 12 X	.85
84 and 91 KDS 11 X	
Cutter	.95
404 Plain	1.00
404 Cutter	1.10
405-12 in. Plain	1.10
405-12 in. Cutter	1.20
405-14 in. Plain	1.20
405-14 in. Cutter	1.30
222X14 in.	1.55
NC 23-14 Q.D.	1.60

Hillside Shares

55-56	\$1.35
155	.70
509-513-524	1.25

Landsides, Right Hand

B WB	\$.75
10 WB	.80
13 WB	.95
19 WB	1.00
20 WB	1.05
40 WB	1.10
B SB	.75
BC SB	.75
10 SB, SF or DF	.80
13 SB, SF or DF	.95
19 SB, SF or DF	1.00
20 SB, SF or DF	1.05
40 SB, SF or DF	1.10
82—F 715	1.45

TO FIT OLIVER

(Landsides, Right Hand
Continued)

82 M—F 763 A	\$1.60
83 DF—F 1304	1.45
84 DF	1.45
F 682 for Sulky	1.45
F 905 small for Trac-	
tor	.70
F 926 A large for	
Tractor	1.60
F 1023 for B 5 Sulky	1.10
B 5	1.00
40 X to fit Gang	1.60
20 X to fit Gang	1.20
3 X	1.60
98 WB—4 holes	1.45
98 SB—5 holes	1.45
NC B5 M	1.20
NC-101 B (F2495)	.70
NC-23 (F1276A)	.70
NC-82 (F762)	.70

Landsides, Left Hand

20 WB	\$1.05
40 WB	1.10
E WB	1.10
10 SB	.80
13 SB	.95
19 SB	1.00
20 SB, SF or DF	1.05
40 SB, SF or DF	1.10
3 X	1.60
83 DF	1.45
F 683 for Sulky	1.45
405	1.45

Moldboards, Right Hand

A	\$1.40
B	2.05
B C	2.05
B 5	4.95
10	2.25

THEY FIT

TO FIT OLIVER

(Moldboards, Right Hand Continued)

13	\$3.00
19	3.25
20	3.40
40	3.75
E	3.75
82	4.00
83	4.50
84	5.00

Moldboards, Left Hand

13	\$3.00
19	3.25
20	3.40
40	3.75
E	3.75
82	4.00
83	4.50
84	5.00
3 X	5.80
405	5.00

Miscellaneous

F 2496 shoe	\$.70
GY 206 shoe to fit No. 101 RH	1.00
B 5 shin	.30

Jointer Shares Right Hand

140—JY 730	\$.35
F 2288	.25
3 X	.35
F 2494	.70

Jointer Shares, Left Hand

150—JY 731	\$.35
F 2289	.25
3 X	.35

TO FIT OLIVER

Jointer Moldboards, Right Hand

140—JY 630	\$.60
3 X	.55

Jointer Moldboards, Left Hand

150—JY 631	\$.60
3X	.55

Woods

19 Wood Beam, RH and LH	\$4.15
20 Wood Beam, RH and LH	4.15
40 Wood Beams, RH and LH	4.15
405 Wood Beams	4.70
40 single handles for RH and LH for wood beam plows ..	.85
405 single handles for wood beam plows	.85

To Fit SYRACUSE

Solid Shares, Right Hand

9	\$.80
9 Gang	.70
1-1878 C or P	.63
1-1878 Contractor	.78
2-1878 C, P or H	.60
3-1878	.56
5-1878	.37
10-1878 C or P	.71
7-1882	.85
31-61-33 H	.90

THEY GIVE SERVICE

TO FIT SYRACUSE

(Solid Shares, Right Hand
Continued)

31 C	\$.75
32-62-34-452 H	.85
32 C	.70
50	.30
51	.33
52	.37
53	.45
54	.75
56 A	.80
72-9 in.	.90
72-11 in.	.95
73-8 in.	.85
73-9 in.	.90
401 C or P	.90
402 C or P	.85
403 C or P	.80
459 DS or CC	.22
1459 DS	.22
601-461-1461 C or P ..	.67
602-462-1462 C or P ..	.63
603-463-1463 C or P ..	.63
604-464-1464 C, P, or CC	.52
605-465-1465 C or CC ..	.45
606-466-1466	.37
467-1467	.30
674-684-484-474	.65
675-685-485-475-1485 ..	.65
1473	.63
1473 ½	.56
1474	.52

Solid Shares, Left Hand

20-1878 C, P or H	\$.63
30-1878 P or H	.65
35	.80
37-38-41-172-192 H	.85
39-40-42-171-191 H	.90

TO FIT SYRACUSE

(Solid Shares, Left Hand
Continued)

96	\$.60
97	.65
301 C or P	.90
302 C or P	.85
501-361-1361 C or P	.67
501-361-1361 H	.82
502-362-1362 C or P	.63
502-362-1362 H	.78
322 ½ -342 ½ -522 ½	
542 ½	1.20

Hillside Shares

60 and 60 A	\$1.15
702-14-16	.82
36-236	.41
26-126-226-26 ½	.63
821	.86
822	.78
6-6L	.82
A Diamond	1.05
B Diamond	1.00
C Diamond	.75

Solid Cutter Shares, Right Hand

1-1878	\$.78
2-1878	.75
3-1878	.71
401	1.05
402	1.00
31-61 H	.90
32-62 H	.85
72	1.05
73-9 in.	1.05

Solid Cutter Shares, Left Hand

20-1878	\$.78
30-1878	.80

THEY ARE WORTH THE PRICE

TO FIT SYRACUSE

(Solid Cutter Shares, L. H.
Continued)

301	\$1.05
302	1.00
37 H	.85
39 H	.90
Landsides, Right Hand	
9	\$1.45
9 Vineyard Gang	.75
1-1878-8-12	.97
2-1878	.93
3-1878	.82
5-1878	.56
10-1878	1.08
50	.63
51	.75
52	.82
53	.93
54	1.40
56 A	1.55
61	1.50
62	1.50
401	1.60
402	1.50
403	1.25
452	1.20
459	.41
1459 or 459L	.48
461-1461	1.12
462-1462	1.12
463-1463	1.05
464-1464	.93
465-1465	.82
466-1466	.75
467-1467	.52
1473	1.16
1473½	1.12
1474-5	1.01
601	1.50
602	1.50

TO FIT SYRACUSE

(Landsides, R. H.
Continued)

602 WP	\$1.35
603	1.40
604	1.25
605	1.10
606	1.00
674-675-475-474	.75

Steel Landsides

31	\$3.00
32	3.00
37	3.00
39	3.00

Landsides, Left Hand

20-1878	\$.93
30-1878	1.08
97	1.70
301	1.60
302	1.50
501	1.50
502	1.50
361-1361	1.12
362-1362	1.12

Shoes

31-33 RH	\$.75
32-34 RH	.70
37-41 LH	.70
39-42 LH	.75
6 Hillside	.90
60-60A Hillside	1.20
226 Hillside	1.00
702 Hillside	1.40
A Diamond Hillside	1.00
B Diamond Hillside	1.00
C Diamond Hillside	.55

Moldboards, Right Hand

2-1878	\$4.12
53 L	3.00

THEY FIT

TO FIT SYRACUSE

(Moldboards, Right Hand Continued)

54 L	\$4.50
56 A	5.00
401	5.25
402	4.75
456	1.42
1459	1.50
601	5.50
602-602L	5.00
603-463-1463	3.37
604-464-1464	3.00
605-465-1465	2.25
606-466-1466	2.06

Moldboards, Left Hand

20-1878	\$4.31
30-1878—30-1880	4.68
501	5.50
502	5.00
361	4.12
362	3.75

Shins, Right Hand

53	\$.50
54	.60
56 A	.70
401	.85
402	.85
403	.65

Shins, Left Hand

97	\$.75
301	.85
302	.85

Jointer Shares, Right Hand

2-78 (CE 6) ribbed back	\$.25
53 (CE 8) ribbed back	.20
S (Flat Back)	.25

TO FIT SYRACUSE

Jointer Shares, Left Hand

20-78 (CE 5) ribbed back	\$.25
S (Flat Back)	.25

Jointer Moldboards, Right Hand

2-78 (CT 8)	\$.50
53 (CT 12)	.50

Jointer Moldboards, Left Hand

20-78 (CT 7)	\$.50
--------------------	--------

To Fit DEERE

Solid Shares, Right Hand

C 215 12 in. QD	\$1.40
C 217 A 14 in. QD	1.65
C 223 DDS QD	1.60
C 256 QD	1.10
C 257 QD	1.25
C 300 A QD	1.45
C 301 A QD	1.65
MC 221 QD	1.40
MC 222 QD	1.55
1441 bolt	.75
1442 bolt	.70
1441 QD	.75
1442 QD	.70
C X 38	.95
C 38	.95
C 37	.80
C 49	.85

Solid Shares, Left Hand

C 223 DDS QD	\$1.60
--------------------	--------

THEY GIVE SERVICE

TO FIT DEERE

(Solid Shares Left Hand
Continued)

1341 bolt	\$.75
1342 bolt	.70
1341 QD	.75
1342 QD	.70

Solid Cutter Shares Right Hand

1441 bolt	.90
1442 bolt	.85
1441 QD	.90
1442 QD	.85

Solid Cutter Shares, Left Hand

1341 bolt	\$.90
1342 bolt	.85
1341 QD	.90
1342 QD	.85

Landsides, Right Hand

1441	\$1.55
1442	1.55
1441 D 3 long	1.10
1441 D 4 short	.70
1442 D 3 long	1.10
1442 D 4 short	.70

Landsides, Left Hand

1341	\$1.55
1342	1.55

Shoes

1441-1442 (FA 2) RH	\$.40
1341-1342 (FA 3) LH	.40

Moldboards, Right Hand

1441	\$5.25
1442	4.75

Moldboards, Left Hand

1341	\$5.25
1342	4.75

TO FIT DEERE

Shins

1441 (CD 18) RH	\$.75
1442 (CD 20) RH	.65
1341 (CD 17) LH	.75
1342 (CD 19) LH	.65

To Fit
WIARD

Solid Shares, Right Hand

D	\$1.00
16-19	.65
17	.70
25-26, 26½ C or Stony	.70
43-44 C or S	.70
43-44 solid cutter	.85
65 D	1.15
72	.80
73	.70
90-91-70-71 C or S	.70
90-91 solid cutter	.85
208-209	.25
210	.30
212	.35
214-215	.40
216	.50
218	.55
219-20	.70
526	.85
1526	.95
100 A	.70

Solid Shares, Left Hand

27-28 C or Stony	\$.70
80-81 C or Stony	.70

THEY ARE WORTH THE PRICE

TO FIT WIARD

(Solid Shares, Left Hand,
Continued)

103-104 C or Stony	\$.70
106 C or Stony	.75
103-104 solid cutter	.85
546	.85
1546	.95

Hillside Shares

Regular or Stony

116	\$.95
126-35	.95
140-130-115-120-300	.85

Landsides, Right Hand

17-18	\$1.25
25-60	1.25
26-26½	1.25
43-44	1.25
45	1.25
90-91	1.00
526-1526	1.55
65 D	1.75
208-209	.60
210	.75
212	.75
214-215	1.00
216	1.10
218	1.25
219-20	1.40

Landsides, Left Hand

14-15	\$1.30
27-28	1.25
80-81	1.00
103-104-106 Landside only	1.25
103-104-106 solid landside	1.55
546-1546	1.55

TO FIT WIARD

Shoes

7-116	\$1.15
43-44	.70
80-81	.70
90-91	.70
103-104-106	.70
120-140	1.15
126-126 X	1.15
130-115X-130X-	
300	1.15

Moldboards, Right Hand

65 A	\$5.50
26½	4.50
44	4.50
90	5.00
72	4.00
208-209	1.10
210	2.00
212	2.25
214-215	3.00
216	4.00
218	4.25
219-20	4.50

Moldboards, Left Hand

28	\$5.00
80	5.00
104	4.50
106	4.75

Jointer Shares

10 RH	\$.25
I J RH	.25
"Pride" RH	.25
40 LH	.25
For Hillside plows	.25

Jointer Moldboards

84 RH	\$.50
6 LH	.50

THEY FIT

TO FIT WIARD

Shins

25-26-26½—60 RH	\$.70
43-44 RH	.70
45 RH	.70
90-91 RH	.70
526-1526 RH	.75
27-28 LH	.70
80-81 LH	.70
103-104 LH	.70
106 LH	.70

To Fit LEROY

Solid Shares, Right Hand

108-70 C or P	\$.75
108 solid cutter share	.90
109-72 C or P	.80
109 solid cutter share	.95
71	.80
110-73-210-93 C or P	.85
110 solid cutter share	1.00
112-114 C or P	.90

Solid Shares, Left Hand

508-70	\$.75
509-72-71	.80
510-73-93	.85
510 solid cutter share	1.00

Hillside Shares

30-31-32-33-34-35	\$.95
-------------------------	--------

Landsides, Right Hand

108-70	\$1.40
109-72	1.50

TO FIT LEROY

(Landsides R. H. Con-
tinued)

71	\$1.50
110-73	1.60
112-114	1.75

Landsides, Left Hand

508-70	\$1.40
509-72	1.50
71	1.50
510-73	1.60
30-31-32 Shoe	1.45

Moldboards, Right Hand

109	\$5.25
110	5.75

Moldboards, Left Hand

509	\$5.25
510	5.75

Shins, Right Hand

108	\$.85
109	.85
110	.95

Shins, Left Hand

508	\$.85
509	.85
510	.95

Jointer Shares and Moldboards

110 RH jointer share	\$.25
510 LH jointer share	.25
110-13 RH jointer moldboards	.50
510 LH jointer mold.. ..	.50

To Fit CAMBRIDGE

10-29 Hillside share.....	\$1.05
60 LH Solid share	.85

THEY GIVE SERVICE

TO FIT CAMBRIDGE

61 LH Solid	\$.90
16A Hillside Shares ..	1.05
16B Hillside Shares	1.00

To Fit P. & O.

Solid Shares, Right Hand

42	\$1.35
46	1.15
48	1.05
50	.95
404 R 10 in.	.95
264	1.15
266	1.35
454	1.40
462	1.60
446	1.60
480	1.60
0554	1.60
0566	1.60
SA 1037	1.60
SA 1040	1.40
SA 1041	1.60
SA 1153-14 in QD	1.60

To Fit BURCH

Solid Shares

21 Right Hand	\$.85
61 Right Hand	.90
22 and 52 H Solid Left Hand	.85

TO FIT BURCH

(Solid Shares Continued)

22 and 52 C, P or H Left Hand	\$.85
22 and 52 solid cutter shares, Left Hand..	1.00
21 solid cutter shares Right Hand	1.00

Landsides

21 Right Hand	\$1.25
22 Left Hand (Solid)	1.50
52 Left Hand (Plain)	1.25
52 Left Hand (Solid)	1.50

Shoes

21 Right Hand	\$.75
22 and 52 Left Hand....	.75

Jointer Shares

21 Right Hand	\$.25
22 Left Hand	.25

Jointer Moldboards

21 Right Hand	\$.45
22 Left Hand	.45

Shins

51 Right Hand	\$.60
52 Left Hand	.60

Moldboards

21 Right Hand	\$5.00
22 Left Hand	5.00
52 Left Hand	5.00

To Fit IMPERIAL

Solid Shares, Right Hand

8-8 in.	\$.45
9-9 in.	.55

GOOD REPAIRS MAKE GOOD PLOWS BETTER

TO FIT IMPERIAL

Solid Shares, Right Hand (Continued)

10-10 in.	\$.60
10-11 in. deep	.60
26-13 in.	.80
26-13 in. cutter	.95
600 X—12 in.	.70
625 X	.70
710 X—700 X	.65
808 X—800 X	.55
808 X CC	.55
807 X	.50
810 X	.65
810 X CC	.65
917 X	.40
917 X CC	.40
927 X	.25
927 X CC	.25

Solid Shares, Left Hand

26-12 in.	\$.95
26-13 in.	.85
26-12 in. cutter	.90
26-13 in. cutter	.95
300 X—12 in.	.70
300 X—13 in.	.75
325 X	.70
400 X	.65

Hillside Shares

5	\$.65
6	.70

Landsides, Right Hand

600 X	\$1.10
625 X	1.10
710 X—700 X	1.05
807 X	.75
808 X—800 X	.95
818 X	.95
810 X	1.00

TO FIT IMPERIAL

Landsides, Right Hand (Continued)

917 X	\$.55
927 X	.50

Landsides, Left Hand

26	\$1.45
300 X	1.10
325 X	1.10
400 X	1.05
400 GA for Tractor.....	1.00

Shoes

5 Hillside	\$1.15
6 Hillside	1.15

Moldboards, Right Hand

600 X	\$4.15
625 X	4.15
710 X—700 X	3.75
807 X	2.25
808 X	3.00
810 X	3.55
917 X	1.60
927 X (large)	1.40

Moldboards, Left Hand

26	\$4.15
300 X	4.15
325 X	4.15
400 X	3.75

Woods

300 X beams, LH	\$4.25
26 beams, LH	4.25
Single handles for No. 26 and 300 X each....	.90

Jointer Shares, Right Hand

J 53	\$.25
Old Style	.50
600 X Reversible	.50

THEY ARE WORTH THE PRICE

TO FIT IMPERIAL

Jointer Shares, Left Hand

J 63	\$.25
Old Style	.50
300 X Reversible	.50

Jointer Moldboards

J 52 R. H.	\$.40
J 62 L. H.	.40

To Fit

INTERNATIONAL

Solid Shares, Right Hand

CP 6002 DS	\$.95
CP 6007 DS	1.00
CP 6152-14 in.	

(Alfalfa) 1.10

H 914 QD, plain 1.10

H 914 QD, with bolts
and lugs 1.20

Solid Shares, Left Hand

CP 6027 DS	\$.95
CP 6028 DS	1.00

Solid Cutter Shares

Right Hand

CP 6122	\$1.35
CP 6123	1.45

Solid Cutter Shares,

Left Hand

CP 6124	\$1.35
CP 6125	1.45

Landsides, Right Hand

CP 6001 (short)	\$.70
CP 6001 M (long)	1.20
CP 6021	1.50

TO FIT INTERNA- TIONAL

Landsides, Left Hand

CP 6022	\$1.50
---------------	--------

Moldboards, Right Hand

CP 6008	\$5.00
CP 6009	5.25

Moldboards, Left Hand

CP 6103	\$5.00
CP 6104	5.25

Shins

CP 6003 R. H.	\$.40
CP 6105 L. H.	.40

Jointer Shares

CPJT 18 R. H.	\$.30
CPJT 24 L. H.	.30
PO 1184 R. H.	.30

Jointer Moldboards

CPJT 19 R. H.	\$.65
CPJT 25 L. H.	.65

To Fit FERGUSON

Solid Shares, Right Hand

12 B 1 (F 204)	\$1.00
10 B 1	1.00
12 A 1 (F 82-12 in.)....	1.10
14 A 1	1.20

Landsides, Right Hand

F 208, long	\$1.00
F 200 for 5 B plow	.60
F 207 X	.60

THEY FIT

To Fit EAST AURORA

(Peck)

S 22 solid plain shares	\$.90
S 22 solid cutter shares	\$1.05
S 22 landside	.95
S 22 jointer point	.25

To Fit JANESVILLE

(Sampson)

Solid Shares, Right Hand AS 14	\$1.25
--------------------------------------	--------

To Fit MUNNSVILLE

Solid Shares

7-A 2½ in.	\$.75
1	.85
5	.85
66A	.90
46-56	.90
10	.90

Solid Cutter Shares

7-A 2½	\$.90
1	1.00
5	1.00

TO FIT MUNNSVILLE

Solid Cutter Shares (Continued)

66A	\$1.10
46-56	1.10
10	1.00

Hillside Shares

14-24-34-95	\$1.15
-------------------	--------

Shins

6 C	\$.60
-----------	--------

Landsides

7	\$1.00
A 2½	1.00
C1	1.40
5	1.10
46-56	1.40
10	1.40
66	1.40
1 Steel	3.00
2½ Steel	2.75
10 Steel	3.00

Shoes

2½	\$.75
1	1.00
10	1.15
66B	1.15
14-95	1.15
24-34	1.15

Moldboards (Chilled)

5	\$5.00
66	5.00
46	5.00
Hillside	5.00

Wheels only	.65
-------------------	-----

GOOD REPAIRS MAKE A GOOD PLOW BETTER

To Fit MOLINE

Solid Shares

14 (WP 2 C) RH	\$.90
14 (WP 44 C) LH	90

To Fit RANDOLPH

Shares

76 A Hillside	\$1.05
76 B Hillside	 1.00
100 H	85

Shoes

76 A	\$1.00
76 B	 1.00

To Fit EDDY

Hillside Shares

21 A	\$1.05
21 B	 1.00

To Fit CHICOPEE

Hillside Shares

A	\$1.05
---	-------------

TO FIT CHICOPEE Hillside Shares (Con- tinued)

B	\$1.00
C	75

Solid Shares, Right Hand	
100 H	\$.85

Shoes

A	\$1.00
B	 1.00
C	55

To Fit PEERLESS

Solid Shares, Left Hand

1	\$.90
2	85

Explanation of Symbols Plow Shares

S	—Stony
DS	—Deep Suck
C	—Common
SNY	—Stony New York
LN	—Long Nose
P	—Pitch or Stony
H	—Heavy
QD	—Quick Detachable
X	—(Oliver) Concave
CC	—(All others) Concave

Landsides

WB	—Wood Beam
SB	—Steel Beam
SF	—Single Flange
DF	—Double Flange