



CRAWFORD'S IMPROVED MOWER & REAPER.
Cazenovia, N.Y.



CRAWFORD'S IMPROVED MOWER & REAPER.
Cazenovia, N.Y.

Price List of Parts.

In ordering parts, give the letter, number or name of piece.

PARTS DESIGNATED BY LETTERS.

	Price.		Price.
A. Brace and Lug.....	\$3.50	L. Lever-hanger	3.00
B. Main Shoe-holder.....	3.75	M. Gear Cover.....	2.00
C. Pitman-holder	1.25	P. Tilting-lever and	
D. Tilting-lever Washer..	.25	Washer.....	2.00
E. or N. Pitman-shaft Box		S. Pitman shaft Cap.....	2.00
each,	.20	T. Gear-shifting Lever....	.35
F. Latch-holder	.50	V. Lever-dog	.20
G. or K. Main Shoe (old cut		W. Main Frame	10.00
G. or new cut K), each	5.00	X. Tilting lever holder..	.75
J. Front brace Connect-		Y. Sickle-holder, small..	.75
ion	2.00		

PARTS DESIGNATED BY FIGURES.

	Price.		Price.
3. Drive Wheel.....	\$8.00	14. Ratchet Pawl.....	.25
4. Pole Tip.....	.50	16. Main Spur gear.....	2.00
5. Lifting-lever Washer..	.25	17. Spur gear and Pinion..	3.00
7. Track-clearer comp...	2.50	18. Bevel gear and Pin-	
10. Pitman Bal. Wheel...	2.00	ion	2.00
13. Pawl-holder, (right or		19. Bevel Pinion.....	.50
left hand), each.....	1.00	20. Cross-shaft Boxes.....	.15

UNMARKED PARTS.

	Price.		Price.
Small Sickle-holder.....	\$.20	Lynch Pin.....	.05
Seat and Tool-box com-		Spring Keys.....	.05
bined	2.50	Hammer Strap Bolt.....	.20
Crank Shaft, complete..	5.00	Spiral Spring for Pawl...	.05
Lifting lever with spring		Rivets, per pound.....	.40
Dog	3.00	Pole	3.00
Pitman, complete	3.50	Evener & Whiffletrees..	2.50
Scythe, complete.....	5.00	Neck Yoke.....	1.50
Section	.15	Pitman Thimble.....	.20
Dividing Shoe, complete..	2.50	Main Axle.....	5.00
Guard	.40	Cross Shaft.....	2.00
Seat Spring	3.25	Finger Bar, plain and	
Screw Wrench, extra.....	1.00	drilled.....	9.00
Guard Bolt.....	.08		

COMPL

CRAWF

CAZ