


PRICE LIST OF PARTS
OF
BUCKEYE MOWERS



AND
BAY STATE RAKES.

MANUFACTURED BY
BUCKEYE MOWING MACHINE COMPANY,
WEST FITCHBURG, MASS.



DRAWN BY WILSON.


PARTS OF NO. 1 MOWER.

J. W. Dorr, N. Y.

In ordering an Extra Part, to supply a breakage, give the Number on the broken Casting, also the size and Number of Machine, with the year of its purchase.

EXTRA PARTS OF BUCKEYE MOWER No. 1.

No.	Price.	No.	Price
0 Spring keys, same as No. 86,	\$0 03	27 Gag for raising bar, -	\$0 50
1 Connecting rod, without boxes, - -	2 50	28 Front hanger and cap, -	5 00
1 a double washer, for do, -	10	Front hanger, without cap, -	4 25
2 Roll and bolt, - -	40	Front hanger cap, - -	75
3 Composition box, (old pattern)	1 25	29 Track clearer, iron (old pattern), - -	1 00
3 a Composition box (new pat.),	1 00	29 a Track clearer, iron with slide, - -	1 25
4 Spring gib, - -	15	29 b Track clearer slide, - -	25
5 Ratchet key, - -	15	30 Back hanger, - -	1 00
6 Inside shoe, - -	3 00	31 Short brace, - -	2 00
7 Outside shoe, - -	2 50	32 Knife button, - -	10
8 Guard finger (rivited), -	50	33 Knife section, - -	20
8 a guard finger (bolted), -	50	33 a Blank section, - -	20
Plate for guard finger, -	15	34 Complete Scythe, - -	6 00
Guard bolt, - -	10	35 Spring pawl (right hand), -	50
9 Driver's seat, - -	1 50	35 a Spring pawl (left hand), -	50
10 Outside shoe spring, -	75	36 Fender for spur wheel, -	75
11 Cross hanger, - -	2 25	37 Fender for bevel pinion, -	30
Cap for do, - -	75	38 Shipper handle, - -	40
12 Crank fender, - -	75	39 Shipper standard, with spring, -	50
Brace for do, - -	25	40 Shipper clutch, - -	50
13 Lever axle, - -	1 00	Shipper yoke, - -	20
14 Box at rear end of crank shaft, - -	1 50	41 Scythe head, - -	1 00
Cap for do, - -	75	Pole, - -	3 00
15 Box at rear end short shaft	1 50	Section rivets per lb, -	25
Cap for do, - -	75	Track clearer sticks each, -	25
16 Lever ratchet, - -	1 00	Axle, with gear and ratchets, -	13 00
17 Back seat spring, - -	75	Axle, without gear and ratchets, -	4 00
18 Main seat spring, - -	3 50	Short shaft, with gears, -	6 00
19 Spur pinion (old pattern), -	1 00	Short shaft, without gears, -	2 00
19 a spur pinion (old pattern), -	1 25	Crank shaft, with balance and spur pinion, -	6 50
20 Driving wheel, - -	8 00	Crank shaft, without balance and spur pinion, -	3 50
21 Bevel pinion, - -	1 00	Finger bar, drilled, without guard or shoes, -	8 00
22 Bevel wheel, - -	5 50	Finger bar with guards, -	18 00
23 Spur wheel, - -	3 50	Finger bar with guards and shoes, - -	25 00
24 Left hand ratchet, - -	1 50	Wrought hinge joint, - -	5 50
24 a left hand ratchet, with sheave, - -	2 00	Lifting chain with eye and nut, -	1 25
24 b right hand ratchet, - -	1 50	Caps for all boxes, - -	75
25 Lea ling wheel, - -	1 75		
26 Crank balance and pin, -	2 50		
Pin for crank balance, -	75		



DRAWN BY WILSON.

PARTS OF NO. 2 MOWFR, 1862 to 1866.

When ordering extra parts to supply breakage, give the number on the broken Casting, when there is one, also the size and number of Machine, with year of purchase.

PRICE LIST OF *PARTS OF No. 2 MOWER.*

(From 1862 to 1866.)

No.	Price.	No.	Price.
50 Driving wheel,	\$7 00	81 Short brace,	\$2 00
51 Spur pinion,	50	82 Front hanger and cap, . .	4 00
52 Bevel do	75	83 Cross hanger and cap, . .	4 00
53 Bevel gear,	4 50	84 Inside shoe,	2 75
54 Internal do,	3 00	86 Spring key,	05
55 Lead wheel,	1 50	87 Box rear end of short shaft,	1 50
56 Lead wheel roll,	30	88 Socket wrench,	35
57 Right hand ratchet, . . .	1 00	89 Cap for cross hanger, (thick)	75
58 Left hand ratchet, . . .	1 00	90 Pole socket,	50
59 Crank balance complete, .	2 50	91 Complete scythe,	5 00
60 Lever ratchet,	1 00	92 Crank fender,	75
61 Composition box,	1 00	Crank fender brace,	50
62 Shipper axle,	25	93 Right hand spring pawl, . .	50
63 Shipper guide,	15	94 Left hand spring pawl, . .	50
64 Shipper lever,	50	95 Lynch pin,	05
65 Shipper clutch,	50	96 Axle washer,	05
66 Shipper button,	10	97 Blank section,	15
67 Finger plate,	15	98 Knife section,	15
68 Finger,	50	99 Axle cap,	50
69 Finger bolt,	10	Double box for front hanger,	
70 Connection rod and box, .	3 50	1865 and 1866,	1 50
71 Hinge joint,	4 50	Front hanger cap 1862 to	
72 Main seat spring,	3 00	1864,	75
73 Back seat spring (narrow),	75	Spiral spring,	20
74 Track clearer iron and slide,	1 25	Wood lever for raising bar,	50
75 Track clearer slide,	25	Outside shoe spring, . . .	75
76 Outside shoe,	2 25	Track clearer bolt,	15
77 Lifting chain,	75	Crank fender bolt,	10
78 Gag iron,	50	Rivets per lb.,	25
79 Lever axle,	1 00	Scythe heads,	1 00
80 Long brace,	2 00	Scythe button,	10

Price List of Parts of No. 3 Mower.

(1862 to 1866.)

Driving wheel,	\$6 00
Inside shoe E,	2 50
Scythes,	4 50

Balance of parts, price same as No. 2:

When ordering, give number on broken casting or number of parts wanted.

Price List of Extra Parts of No. 2 Mower.

Built 1867, '68, '69 and '70.			Not on Diagram.		
No.		Price.	No.		Price.
100	Front hanger, (no cap),	\$3 25	121	Short shaft with gears,	6 00
101	Back hanger, (no cap),	4 50	122	Short shaft without gears,	2 00
102	Front hanger cap, -	75	123	Crank shaft with balance and pinion, - -	6 00
103	Back hanger crank shaft cap,	75	124	Crank shaft without balance and pinion, - -	2 50
104	Back hanger short shaft cap,	75	125	Scythe head, - -	1 00
106	Spur gear, - -	3 00	126	Seat, - -	1 50
107	Spur pinion, - -	75	127	Pin for crank balance, -	75
108	Finger bar rest, - -	25	128	Finger bar drilled, -	7 00
109	Bevel gear guard, -	25	129	Finger bar with fingers,	16 00
110	Crank balance complete,	2 50	130	Finger bar with fingers and shoes - - -	22 50
111	Shipper hanger, - -	50	131	Leaf to main seat spring, wide, - - -	1 50
112	Shipper lever, - -	50		Pole strap, - - -	30
113	Shipper clutch, - -	50		External gear guard, -	1 00
114	Shipper spring, - -	50		Scythe, 4½ feet, - -	5 00
115	Lever axle, - -	1 25		Scythe, 4 feet, - -	4 50
116	Lever ratchet, - -	1 00		Scythe, 3½ feet, - -	4 00
117	Foot trip, - -	25		Sections, - - -	12 ½
118	Foot pawl, - -	25			
119	Main axle with gears and ratchet, - - -	11 00			
120	Main axle without gears or ratchet, - - -	3 50			

PRICE LIST OF PARTS OF NO. 3 MOWER.

Driving wheel, - - -	\$6 00	Inside shoe (malleable), -	\$3 00
Scythe, - - -	4 50	Balance parts, price same as No. 2.	

PRICE LIST OF PARTS OF NEW MODEL BUCKEYE-1871.

Frame, - - -	\$11 00	U Second finger, - -	\$0 50
A Bevel gear, - - -	3 50	V Common finger, - -	50
B Spur gear and bevel pinion, -	3 00	W Spur gear guard, - -	1 50
C Spur pinion, - - -	75	X Connection box, - -	1 00
D Left hand ratchet, - -	1 00	Y Clamp collar for axle, -	50
E Right hand ratchet, - -	1 00	Bevel gear guard, - -	75
F Crank balance complete, -	1 50	Main seat spring, - -	2 00
G Inside shoe, - - -	2 75	Spring under seat (each), -	50
H Lead wheel, - - -	1 00	Scythe head, - - -	75
I Outside shoe, - - -	2 25	Finger bar rest, - - -	25
J Track clearer iron and slide, -	1 25	Tool box cover, - - -	75
K Lever axle, - - -	75	Evener, - - -	1 00
L Lever cam, - - -	75	Whiffletrees, each, - -	75
M Lever pawl, - - -	25	Neck yokes, - - -	1 50
N Lever handle, - - -	35	Scythe, 4½ feet, - - -	4 50
O Seat springs holder, - -	1 00	Scythe, 4 feet, - - -	4 00
P Seat springs holder cap, -	25	Scythe, 3½ feet, - - -	3 50
Q Shipper stand, - - -	25	Thills complete, - - -	6 00
R Shipper clutch, - - -	25	Thills, each, - - -	1 50
S Shipper lever, - - -	25	Draw hook, - - -	50
T Inside finger, - - -	50		

For parts not named, see No. 2 List.

PRICE LIST

OF

Parts of Bay State Rake.

No.	Price.	No.	Price.
1 Clutch for 1871, - -	\$0 75	26 Coil spring, - -	\$0 25
1 a Clutch for 1869, - -	75	27 Loop bolt, 1869, - -	20
2 Clutch cup, 1871, - -	50	28 Loop bolt, 1870, - -	20
2 a Clutch cup, 1867 to 1870,	50	29 Axle arm, 1871, - -	1 00
3 Roller arm, - - -	50	30 Axle arm, 1869, - -	1 00
4 Shieve roll, - - -	25	31 Axle washer, - - -	05
5 Lower gear guard, - -	30	32 Linch pin, - - -	05
6 Upper gear guard, - -	20	33 Head hook, - - -	25
7 Clasp cap, 1870, - -	50	34 Right hand clearer iron,	
7 a Clasp cap, 1869, - -	25	1868, - - -	1 50
8 Left hand clasp, 1870, -	50	35 Left hand clearer iron,	
8 a Left hand clasp, 1869, -	50	1868, - - -	1 50
11 Right hand clasp, 1870, -	75	36 Outside tooth, 1870, -	75
11 a Right hand clasp, 1869,	75	37 Second tooth, 1870, -	75
12 Hold-down iron, 1870, -	50	38 Third tooth, 1870, -	75
13 Hold-down iron, 1869, -	75	39 Fourth tooth, 1870, -	75
14 Gear, - - -	75	40 Common tooth, 1870, -	75
15 Roll cap, 1869, - -	20	41 Foot lever, - - -	75
16 Small hold-down iron, -	25	42 Hold-down lever, - -	75
17 Gear guard, 1869, - -	75	43 Short shaft, 1870, - -	50
18 Tooth holder, 1870, - -	25	44 Short shaft, 1869, - -	50
19 Tooth holder, 1869, - -	25	45 Seat spring, each, - -	75
20 Shipper, - - -	25	46 Hand lever, - - -	75
21 Loop brace, - - -	50	47 Shipper roll, . . .	1 00
22 Clutch spring, 1870, - -	25	48 Clearer stick, . . .	20
23 Clutch spring, 1869, - -	25	49 Loop bar, . . .	1 50
24 Head spring, - - -	50	50 Clearer bar, . . .	2 00
25 Head spring leaf, - -	25		

In ordering Teeth, give number of Rake and year of purchase; and give number of parts on diagram for any part wanted.



PARTS OF BAY STATE RAKE.