


PRICE LIST OF PARTS

—OF—

Benjamin & Buel

MOWERS,



[SHOWING THE WORKING PARTS OF THE MACHINE.]

MANUFACTURED BY
R. A. LEONARD,
WEST FITCHBURG, MASS.

SENTINEL PRINTING COMPANY, FITCHBURG.

PRICE LIST OF DUPLICATE PARTS

—FOR—

KENYON MOWERS.

In ordering Parts to supply breakages, give No. on broken casting and state if for one or two horse machine.

	Main Frame,	\$8 00	Track Clearer Sticks,	\$ 20
A 2	Top Frame,	5 00	Track Clearer Irons,	1 00
B 2	Shoe and Pipe,	5 00	Shipper Handle,	50
C 2	Lever Cam,	1 25	Shipper Clutch, steel,	1 25
D 2	Right Hand Ratchet,	75	Shipper Spring,	50
E 2	Left Hand Ratchet,	75	Seat Spring,	1 25
F 2	Spur Gear,	2 50	Seat Spring Leaf,	60
G 2	Bevel Gear and Spur Pinion,	2 50	Seat,	1 25
	Bevel Pinion,	75	Drive Wheel,	5 50
H 2	Bevel Gear Guard,	1 50	Wheel Pawl,	10
I 2	Spur Pinion Guard,	75	Pawl Lifters,	10
J	Spur Gear Guard,	1 50	Pawl Springs,	10
K	Shipper Lever Axle,	50	Linch Pins,	5
L	Crank Balance, complete,	1 25	Axle Washers,	5
	Crank Balance,	75	Scythe Buttons,	10
M	Lever Pawl,	10	Inside Guard Fingers,	30
	Crank Fender,	1 25	Common Guard Fingers,	30
	Connection Rod and Box,	1 50	Outside Shoe,	1 75
	Connection Box,	75	“ “ Wheel,	25
	Quadrant, steel,	1 25	“ “ “ Roll,	15
	Scythe Head,	75	“ “ Guard,	50
	Sections,	10	Thills, complete,	6 00
	Complete Scythe, 4 ft. 6 in.	4 00	“ each,	1 50
	“ “ 4 ft.	3 50	Stub Socket,	1 25
	“ “ 3½ ft.	3 00	Evener,	1 00
	Lead Wheel,	75	Neck Yoke,	1 50
	Finger Bar with Fingers,	1 00	Whiffletrees, each,	75
	Cold Chisel,	25	Wood Lever,	40
	Punch,	10	Pole,	3 00
	Latch Handle,	25	“ Socket,	50
	Latch Rod,	15	Finger Guard Bolts,	8
	Rivets, per lb.,	25	Inside Shoe “	10
	Tool Box Cover,	50	Outside “ “	10
	Lead Wheel Roll,	25	Other Bolts,	15

Parts for No. 3 Mower correspond with parts for No. 2.

PRICE LIST OF BUCKEYE EXTRA PARTS OF NO. 2 MOWER.

Built 1867, '68, '69 and '70.

No.	Price.
100 Front hanger, (no cap)	\$3 25
101 Back hanger, (no cap)	4 50
102 Front hanger cap,	75
103 Back hanger crank shaft cap,	75
104 Back hanger short shaft cap,	75
106 Spur gear,	2 50
107 Spur pinion,	70
108 Finger bar rest,	25
109 Bevel gear guard,	25
110 Crank balance, complete,	1 75
111 Shipper hanger,	50
112 Shipper lever,	50
113 Shipper clutch,	50
114 Shipper spring,	50
115 Lever axle,	1 00
116 Lever ratchet,	1 00
117 Foot trip,	25
118 Foot pawl,	25
119 Main axle with gears and ratchet,	10 00
120 Main axle without gears or ratchet,	2 50

Not on Diagram.

No.	Price.
121 Short shaft, with gears,	\$6 00
122 Short shaft, without gears,	2 00
123 Crank shaft, with balance and pinion,	6 00
124 Crank shaft, without balance and pinion,	2 00
125 Scythe head,	1 00
126 Seat,	1 25
127 Pin for crank balance,	75
128 Finger bar, drilled,	6 00
129 Finger bar, with fingers,	14 00
130 Finger bar, with fingers and shoes,	20 00
131 Leaf to main seat spring, wide,	1 25
Pole strap,	30
External gear guard,	1 00
Scythe, 4½ feet,	4 50
Scythe, 4 feet,	4 00
Scythe, 3½ feet,	3 50
Sections,	12


PRICE LIST OF PARTS OF NO. 3 MOWER.

Driving wheel,	\$5 00	Inside shoe, (malleable)	\$3 00
Scythe,	3 50	Balance parts, price same as No. 2.	

PRICE LIST OF PARTS OF NEW MODEL BUCKEYE---1871.

Frame,	\$8 00	U Second finger,	30
A Bevel gear,	2 50	V Common finger,	30
B Spur gear and bevel pinion,	2 00	W Spur gear guard,	1 25
C Spur pinion,	60	X Connection box,	1 00
D Left hand ratchet,	75	Y Clamp collar for axle,	30
E Right hand Ratchet,	75	Bevel gear guard,	75
F Crank balance complete,	1 25	Main seat spring,	1 50
G Inside shoe,	2 25	Spring under seat (each)	25
H Lead wheel,	1 75	Scythe head,	75
I Outside shoe,	1 75	Finger bar rest,	15
J Track clearer, iron and slide,	1 00	Tool box cover,	75
K Lever axle,	60	Everer,	1 00
L Lever cam,	60	Whiffletrees, each,	75
M Lever pawl,	25	Neck yokes,	1 50
N Lever handle,	35	Scythe, 4½ feet,	4 00
O Seat springs holder,	1 00	Scythe, 4 feet,	3 50
P Seat springs holder cap,	25	Scythe, 3½ feet,	3 00
Q Shipper stand,	20	Thills, complete,	6 00
R Shipper clutch,	20	Thills, each,	1 50
S Shipper lever,	20	Draw hook,	50
T Inside finger,	30	For parts not named, see No. 2 List.	

When ordering, give number on broken casting or number of parts wanted.



THE BUCKEYE MOWER.


When ordering extra parts to supply breakage, give the number on the broken casting, when there is one; also, the size and number of Machine, with year of purchase.

PRICE LIST OF
PARTS OF NO. 2 MOWER.
(From 1862 to 1866.)

No.	Price.	No.	Price.
50 Driving wheel,	\$6 00	81 Short brace,	\$2 00
51 Spur pinion,	50	82 Front hanger and cap,	4 00
52 Bevel do.,	75	83 Cross hanger and cap,	4 00
53 Bevel gear,	3 50	84 Inside shoe,	2 75
54 Internal do.,	3 00	86 Spring key,	3 00
55 Lead wheel,	1 00	87 Box rear end of short shaft,	1 50
56 Lead wheel roll,	25	88 Socket wrench,	35
57 Right hand ratchet,	75	89 Cap for cross hanger, (thick)	75
58 Left hand ratchet,	75	90 Pole socket,	50
59 Crank balance, complete,	2 50	91 Complete scythe,	4 50
60 Lever ratchet,	1 00	92 Crank fender,	75
61 Composition box,	1 00	Crank fender brace,	50
62 Shipper axle,	25	93 Right hand spring pawl,	50
63 Shipper guide,	15	94 Left hand spring pawl,	50
64 Shipper lever,	25	95 Linch pin,	5
65 Shipper clutch,	50	96 Axle washer,	5
66 Shipper button,	10	97 Blank section,	12
67 Finger plate,	10	98 Knife section,	12
68 Finger,	30	99 Axle cap,	50
69 Finger bolt,	8	Double box for front hanger,	
70 Connection rod and box,	2 50	1865 and 1866,	1 50
71 Hinge joint,	4 50	Front hanger cap, 1862 to	
72 Main seat spring,	2 00	1864,	75
73 Back seat spring, (narrow)	75	Spiral spring,	20
74 Track clearer iron and slide,	1 00	Wood lever for raising bar,	50
75 Track clearer slide,	25	Outside shoe spring,	50
76 Outside shoe,	2 00	Track clearer bolt,	15
77 Lifting chain,	75	Crank fender bolt,	10
78 Gag iron,	25	Rivets, per lb.,	25
79 Lever axle,	1 00	Scythe heads,	75
80 Long brace,	1 00	Scythe button,	10

Price List of Parts of No. 3 Mower. (1862 to 1866.)

Driving wheel,	-	-	-	-	-	\$5 00
Inside shoe E,	-	-	-	-	-	2 00
Scythes,	-	-	-	-	-	3 50
Balance of parts, price same as No. 2.						



PRICE LIST

—OF—

Parts of Bay State Rake.


No.	Price.	No.	Price.
1 Clutch for 1871,	75	26 Coil spring,	25
1 a Clutch for 1869,	75	27 Loop bolt, 1869,	20
2 Clutch cup, 1871,	50	28 Loop bolt, 1870,	20
2 a Clutch cup, 1867 to 1870,	50	29 Axle arm, 1871,	1 00
3 Roller arm,	50	30 Axle arm, 1869,	1 00
4 Shieve roll,	25	31 Axle washer,	5
5 Lower gear guard,	30	32 Linch pin,	5
6 Upper gear guard,	20	33 Head hook,	25
7 Clasp cap, 1870,	50	34 Right hand clearer, iron,	
7 a Clasp cap 1869,	25	1868,	1 50
8 Left hand clasp, 1870,	50	35 Left hand cleaner, iron,	
8 a Left hand clasp, 1869,	50	1868,	1 50
11 Right hand clasp, 1870,	75	36 Outside tooth, 1870,	75
11 a Right hand clasp, 1869,	75	37 Second tooth, 1870,	75
12 Hold-down iron, 1870,	50	38 Third tooth, 1870,	75
13 Hold-down iron, 1869,	75	39 Fourth tooth, 1870,	75
14 Gear,	75	40 Common tooth, 1870,	75
15 Roll cap, 1869,	20	41 Foot lever,	75
16 Small hold-down iron,	25	42 Hold-down lever,	75
17 Gear guard, 1869,	75	43 Short shaft, 1870,	50
18 Tooth-holder, 1870,	25	44 Short shaft, 1869,	50
19 Tooth-holder, 1869,	25	45 Seat spring, each,	75
20 Shipper,	25	46 Hand lever,	75
21 Loop brace,	50	47 Shipper roll,	1 00
22 Clutch spring, 1870,	25	48 Clearer stick,	20
23 Clutch spring, 1869,	25	49 Loop bar,	1 50
24 Head spring,	50	50 Clearer bar,	2 00
25 Head spring leaf,	25		

4 Clutch cup 2.00

4 Clasp 75 3.00

5.00

ONE-HORSE
KENYON,



IN WORKING ORDER.